



CONFIGURATION 1: 110V AT 6A  
 CONFIGURATION 2: 230V AT 6A \*

\* AT 230V THE FOLLOWING CHANGES ARE MADE:  
 1. 230V-110V STEP-DOWN TRANSFORMER (P/N: MS2002CEAX) IS INSTALLED AT RED TRIANGLE ▲  
 2. 12 VDC POWER SUPPLY SWITCH MOVED FROM 110V TO 230V  
 3. COMPUTER POWER SUPPLY SWITCH IS MOVED FROM 110V TO 230V  
 4. 24V POWER SUPPLY AND 22" MONITORS AUTO SWITCH  
 5. FUSE STAYS AT 6A

IA1000X - ICE AGE WIRING DIAGRAM